# PRODUCT INFORMATION PACKET

Model No: 170040.00
Catalog No: 170040.00
General Purpose Motor, 50 & 40 HP, 3 Ph, 60 & 50 Hz, 208-230/460 & 190/380 V, 3600 & 3000 RPM, 324TS Frame, DP

## Nameplate Specifications

| | | | |
|---|---|---|---|
| Phase | 3 | Output HP | 50 & 40 Hp |
| Output KW | 37.0 & 30.0 kW | Voltage | 208-230/460 & 190/380 V |
| Speed | 3560 & 2960 rpm | Service Factor | 1.15 & 1.15 |
| Frame | 324TS | Enclosure | Drip Proof |
| Thermal Protection | No Protection | Efficiency | 94.1 & 93 % |
| Ambient Temperature | 40 °C | Frequency | 60 & 50 Hz |
| Current | 123-112/56 & 108/54 A | Power Factor | 88.6 |
| Duty | Continuous | Insulation Class | F |
| Design Code | B | KVA Code | G |
| Drive End Bearing Size | 6312 | Opp Drive End Bearing Size | 6312 |
| UL | Recognized | CSA | Y |
| CE | N | IP Code | 23 |
| Number of Speeds | 1 | | |

## Technical Specifications

| | | | |
|---|---|---|---|
| Electrical Type | Squirrel Cage Inverter Rated | Starting Method | Wye Start Delta Run Or Inverter |
| Poles | 2 | Rotation | Reversible |
| Resistance Main | .137 Ohms | Mounting | Rigid Base |
| Motor Orientation | Horizontal | Drive End Bearing | Ball |
| Opp Drive End Bearing | Ball | Frame Material | Cast Iron |
| Shaft Type | TS | Overall Length | 24.53 in |
| Shaft Diameter | 1.875 in | Shaft Extension | 3.75 in |
| Assembly/Box Mounting | F1 Only | | |
| Connection Drawing | 004172.01 | Outline Drawing | 16955560 |




| FRAME DESIGN | "C" |
|---|---|
| 324TS | 24.53 |
| 326TS | 26.02 |

| NO. | REVISION | BY & DATE | CHK |
|---|---|---|---|
| 02 | 326TS FRAME WAS 6 HOLES & REMOVED LEESON LOGO | LST 10/2/02 | |
| 01 | REVISED TO NEW BORDER FORMAT | DWF 12/14/01 | |

TOLERANCES UNLESS SPECIFIED

| DEC. | INCHES |
|---|---|
| .X | ±.1 |
| .XX | ±.03 |
| .XXX | ±.005 |
| .XXXX | ±.0005 |
| ANG | ±1/2° |

LEESON ELECTRIC MOTORS GEARMOTORS AND DRIVES

TITLE: OUTLINE 320TS DRIP PROOF – RIGID

MAT'L.: CAST IRON

FINISH:

RFP:

DIST:

CAD FILE: 16955560

| | |
|---|---|
| DRAWN | JJK 04/05/99 |
| CHK | JK 04/06/99 |
| APPD | PG 04/07/99 |
| SCALE | 1=4 |
| REF | 169518 |
| FMF | |
| PREV | |

SIZE: B | DRAWING NO.: 169555-60 | REV.: 02

004172-01

## WYE – DELTA STARTING USEABLE ON 2,4 AND 6 POLE MOTORS.

### LOW VOLTAGE CONNECTION




### HIGH VOLTAGE CONNECTION




REFER TO THE WYE–DELTA STARTER CONNECTION INSTRUCTIONS FOR PROPER CONNECTION OF POWER LINES TO STARTER.

## PART WINDING START USABLE ON 4 & 6 POLE MOTORS
LOW VOLTAGE CONNECTION ONLY




REFER TO THE PART WINDING STARTER INSTRUCTIONS FOR PROPER CONNECTION OF POWER LINES TO STARTER.

REFER TO THE CUTLER – HAMMER OR EQUIV. FOR PROPER SELECTION OF OVERLOAD HEATER COILS.

## LINE LEADS




ROTATION CAN BE REVERSED BY INTERCHANGING ANY TWO LINE LEADS

⦿ RED LEADS OR P1, P2, FOR N/C THERMOSTAT

ACROSS THE LINE START & RUN

| | LINE 1 | LINE 2 | LINE 3 | JOIN & INSULATE SEPARATELY |
|---|---|---|---|---|
| HIGH VOLT | T1,T12 | T2,T10 | T3,T11 | (T4,T7) (T5,T8) (T6,T9) |
| LOW VOLT | T1,T6 T7,T12 | T2,T4 T8,T10 | T3,T5 T9,T11 | |

| NO. | REVISION | BY & DATE | CHK |
|---|---|---|---|
| 03 | REV'D LOW VOLTAGE CONN. LEADS PER ELEC. | BJB 06/07/00 | |
| 02 | ADDED T–STAT. NOTES PER ELECTRICAL | KMM 06/02/98 | |
| 01 | REDRAWN TO CAD | DBT 06/02/97 | |

TOLERANCES UNLESS SPECIFIED

| DEC. | INCHES |
|---|---|
| .X | ±.1 |
| .XX | ±.01 |
| .XXX | ±.005 |
| .XXXX | ±.0005 |
| ANG | ±1/2° |

LEESON ELECTRIC MOTORS GEARMOTORS AND DRIVES

TITLE DELTA – WYE CONNECTION DIAGRAM

MAT'L.

FINISH

CAD FILE 00417201

RFP

DIST

| | |
|---|---|
| DRAWN | WLW 09/08/77 |
| CHK | RPB 09/12/77 |
| APPD | JCW 09/12/77 |
| SCALE | 1=1 |
| REF | |
| FMF | |
| PREV | |

SIZE A | DRAWING NO. 004172–01 | REV. 03



6/28/2007 3:22:15 PM -